

FIG. 1




FIG. 2




Figure 1 is a cross-sectional view of a mechanical assembly. A central shaft 10 is shown with a sleeve 12 and a collar 16. A force F_1 is applied to the left. Dimensions $\delta 1$ and $\delta 2$ are indicated. Labels 4, 18, 22, 24, 25, and 26 point to various components. Section lines A-A, B-B, and C-C are shown at the bottom.

FIG. 3 (5)

